

Attachment A: Digital Images

Page 1 of 6

March 10th, 2008

BOE Building 23rd Floor South

Sacramento, CA



- 1) Image of ambient air sampling location at front entry of BOE Building (Subject Building) located at 450 N Street, Sacramento, California at time of assessment.



- 2) Image of Ambient air sampling location on balcony of 23 south with HTI technician collecting parallel samples.



- 3) Image of 12 Floor southeastern balcony during ambient air collection procedures at time of assessment.



- 4) Image of hallway air sampling within construction offices location (outside containment) adjacent to 23 South containment area at time of assessment.



- 5) Image within 23rd Floor south containment area indicating location of air sampling equipment and “parallel” HTI technician activities.



- 6) Image of encased column located at exterior perimeter wall within 23 South containment area following wallboard removal.



- 7) Close-up image of perimeter wall structures indicating evidence of prior water intrusion (corrosion on floor sill metal) following removal of damaged wallboard materials.



- 8) Wide angle image of 23South containment space indicating ventilation ducting and contained ceiling structures at time of assessment.



9) Additional image of air handling equipment location within 23 south containment area and exposed concrete subflooring present at time of assessment.



10) Image of air sampling equipment within eastern corner of 23 South containment area.



11) Additional image of exposed wall metal framing located at eastern corner of 23 South containment area.



12) Image of air sampling equipment located at exterior hallway of 23 South containment. Sample collected outside containment structures.